

From: [McAteer, Mike](#)
To: [Powell, Greg](#)
Subject: FW: Mayflower Arkansas Oil Spill
Date: Thursday, April 04, 2013 3:05:53 PM

Greg:

Can I please get your input here.... are we asking for the wrong analysis on the Exxon oil from the USCG lab?

thanks

Mike McAteer, OSC
214 354 9371

From: Kristy.L.Juaire@uscg.mil [Kristy.L.Juaire@uscg.mil]
Sent: Thursday, April 04, 2013 2:47 PM
To: Duty-Watch, MSL MSTC; t.a.walzer@westonsolutions.com
Cc: Rhotenberry, William; McAteer, Mike
Subject: RE: Mayflower Arkansas Oil Spill

Good afternoon,

MSL is not able to conduct the analyses you describe below. Our methodology is qualitative for the purpose of fingerprinting and correlating petroleum samples. MSL does not generate quantitative data.

Please let me know if you have any additional questions!

Kristy

Kristy Juaire
Forensic Chemist, CG MSL
860-271-2784

-----Original Message-----

From: T.A <<image001.jpg>> .Walzer@westonsolutions.com [<mailto:T.A.Walzer@westonsolutions.com>]
Sent: Wednesday, April 03, 2013 7:50 PM
To: Duty-Watch, MSL MSTC
Cc: 'William M. Rhotenberry (rhotenberry.william@epa.gov)'; 'Mike McAteer (mcateer.mike@epa.gov)'; Warr (Kettler), Kristie
Subject: Mayflower Arkansas Oil Spill

What is the procedure for sending you a sample of oil from Mayflower, Arkansas spill?

I have been tasked by EPA OSC William Rhotenberry with collecting an oil sample from the pipeline and sending it to you for analysis. They are looking for an analysis for :

API Gravity

Specific Gravity

Target Compound List (SVOC, VOC)

Target Analyte List (Metals)

Have you already been contacted about running an analysis of a sample for the spill in Mayflower Arkansas?

Thomas Walzer

Principal Project Scientist

Weston Solutions, Inc.

an employee-owned company

5599 San Felipe, Suite 700

Houston, Texas 77056

(713) 985.6741 Direct

(713) 705.1467 Cell

(713) 985.6703 Fax

t.a.walzer@westonsolutions.com <<mailto:t.a.walzer@westonsolutions.com>>

Disclosure or use of any such confidential or proprietary information without the written permission of Weston Solutions, Inc. is strictly prohibited. If you received this email in error, please notify the sender by return e-mail and delete this email from your system. Thank you.

***** ATTACHMENT NOT DELIVERED

This Email message contained an attachment named
image001.jpg
which may be a computer program. This attached computer
program could
contain a computer virus which could cause harm to EPA's
computers,
network, and data. The attachment has been deleted.

This was done to limit the distribution of computer viruses
introduced
into the EPA network. EPA is deleting all computer program
attachments
sent from the Internet into the agency via Email.

If the message sender is known and the attachment was
legitimate, you
should contact the sender and request that they rename the
file name
extension and resend the Email with the renamed attachment.
After
receiving the revised Email, containing the renamed
attachment, you can
rename the file extension to its correct name.

For further information, please contact the EPA Call Center at
(866) 411-4EPA (4372). The TDD number is (866) 489-4900.

***** ATTACHMENT NOT DELIVERED
